



Dealer 47T-19
July 23, 1947

To: REGIONS, ZONES, AND DEALERS

Subject: KICKDOWN SWITCH SHORTAGE

Due to a temporary shortage of kickdown switches, part number 347496, some overdrive equipped cars shipped after June 25th do not have these switches installed.

On cars shipped short the kickdown switch, the two leads ordinarily attached to the switch are connected and taped together.

Sufficient switches to equip all cars shipped short will be forwarded automatically to Zones as soon as switches are available.

Dealers should install switches on all cars shipped without them using switches from their service parts stock whenever possible. If the kickdown switch cannot be installed before the car is delivered, the purchaser should be advised of the shortage and informed that it will be installed as soon as available.

Labor and material credit will be allowed for the installation of kickdown switches. When the switches are installed, issue a Request for Adjustment, Form V-487, which will be handled on a theoretical return basis for material. Credit will be allowed for the switches and a labor allowance at 1/2 the Dealer's registered labor rate will be made for 0.3 hour for each switch.

Very truly yours,

A handwritten signature in blue ink that reads "N. A. Lull".

N. A. Lull
Service Technical Manager

NAL:ps