PACKARD MOTOR CAR COMPANY

PHILADELPHIA ZONE OFFICE

Phone: Stevenson 7-8000

1237 North Broad Street
Philadelphia 22, Pa.

February 13, 1953

To: PACKARD DEALERS

Subject: FURTHER INSTRUCTIONS ON
26TH SERIES DIFFERENTIAL PINION BEARING PRELOAD - CAMPAIGN

Gentlemen:

After resetting the pinion bearing preload, the driver's side of differential housing should be marked with a two inch stripe of yellow paint at the pinion shaft end. This will identify the car as having been campaigned.

All RFAs should read as the reason "Correcting Pinion Bearing Preload - Campaign," and you will receive $2.00 on each RFA after they have been properly checked and approved by your Service Representative.

Yours very truly,

M. New

M. New
Zone Service Manager

MN-GM