



Dealer 47MT-2  
August 25, 1947

To: REGIONS, ZONES, DEALERS AND MARINE ENGINE DEALERS

Subject: SUBSTITUTE MARINE ENGINE MOUNTS

Due to a temporary shortage of rubber engine mounts, part numbers MA68457 and MA68876, solid mounts, are being shipped at the present time.

Each engine shipped with these solid mounts carries a tag. The information appearing on this tag is as follows:

### NOTICE

This engine is equipped with solid motor mounts instead of rubber. If solid mounts are not desired, they will be exchanged for rubber mounts, at no extra cost, upon return of this notice with proper identification.

The following information should be typed on the reverse side of the tag.

Engine Model \_\_\_\_\_

Engine Number \_\_\_\_\_

Owner's Name \_\_\_\_\_

The selling Dealer will, on presentation of the tag properly filled out and the solid mounts, furnish the owner with the rubber mounts at no charge.

Full credit will be allowed for the solid mounts when the tag is returned with the Request for Adjustment Form V-487.

Very truly yours,

A handwritten signature in blue ink that reads "N. A. Lull".

N. A. Lull  
Service Technical Manager

NAL:ps