



Dealer 47T-27
November 20, 1947

IMPORTANT

To: REGIONS, ZONES, AND DEALERS

Subject: BRAKE MASTER CYLINDERS ONLY PARTIALLY FILLED

Starting immediately all cars will be shipped from the Factory with the master cylinders only partially filled with brake fluid. This is being done to prevent damage to paint due to leakage of brake fluid from the master cylinders of top deck cars onto those below.

These cylinders should be filled before the cars are driven to assure good brakes and to prevent the entrance of air into the hydraulic system.

Very truly yours,

N. A. Lull
Service Technical Manager

MS

IMPORTANT