

This is an extraction of the turn signal circuit used from 48-56.

Basic colors used were the same for all years but there were inline connectors near the individual lamp assemblies where a color change might happen. There were minor changes elsewhere in 55-6.

